

TO: SERVICE MANAGER TECHNICIANS
PARTS MANAGER

No. 90-10

Incorrect Engine Maximum RPM on Serial Number Plate

Models

MCM D254 Turbo AC Stern Drive Engines
MIE D254 Turbo AC Inboard Engines
Serial Number: C849804 and below

Problem

The serial number plate (attached to the heat exchanger) gives 3800 1/MIN as maximum engine RPM instead of 3600 1/MIN. Prop engines to 3600 RPM (as stated in Installation and Operator Manuals) because there is a significant loss of power between 3600 and 3800 RPM.

Correction

Please make 3800 1/MIN unreadable on serial plate. Because of stamped serial number in plate, a new plate is not to be installed.