

Circulate to: Sales Manager Accounting Service Manager Technician Parts Manager

2.0L Tier 3 SmartCraft Integration Module (SIM) Reflash

NOTICE

This service bulletin supersedes the previous service bulletin number 2015-66/OEM 2015-65 July 2015.

Models Affected

Models Covered	Serial Number
Mercury Diesel 2.0L, 130/150/170 HP, Tier 3 Bravo Sterndrive	All
Mercury Diesel 2.0L, 115/130/150/170 HP, Tier 3 Inboard	All

Scope

Worldwide

Situation

A generic J1939 fault may occur when starting the affected models. This fault is false. Therefore, no problem exists with the engine package. The software has been revised to turn off this fault.

Inspection

Use CDS G3 to verify that the fault occurs on the affected models.

Correction

Perform a reflash of the SIM with CDS G3 1.7.2 or higher. Follow the instruction described in the G3 reflash package.

After the reflash procedure has been completed, a sea trial must be performed to verify the operation of the engine and drive functions.

Warranty

Complete a warranty claim listing:

- Engine serial number
- Labor: 1.0 hour
- Flat rate code: SB10
- Part code: 731
- Fail code: 00

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.