

# service bulletin

No. 93-10

## MERCURY. PERFORMANCE OUTBOARDS

## MHP 2.5 Spark Plug Change

### **MODELS:**

MHP 2.5 EFI/EFI Offshore with 11350A37 ECU Box

#### STARTING WITH SERIAL NUMBER:

0D935175 and up

1994 2.5 EFI engines have a new ECU (P/N 11350A37) which has an internal TPI (Throttle Position Indicator). Any 2.5 with the 11350A37 ECU must use BUZHW spark plugs. The new ECU requires these spark plugs because it is very sensitive to Radio Frequency Interference (RFI).

**BUZHW Spark Plug Part Number: 33-14103550** 

Printed in U.S.A. 93-10 1193