service bulletin

☐ WARRANTY INFORMATION☐ PARTS INFORMATION	√ SEI	RVICE INFORMATIO	N Bul	letin No. 2002-18
Circulate to: Sales Manager A	Accounting	Service Manager	Technician	Parts Manager


Paint Wear

Models Affected

MST9205BF, MST9235BF

Situation

If a 20.5 or 23.5 Gator Breakaway Bracket mount is in the stow position, the bolt head (MRK02503) will rub paint off of the bracket.



00299


a - Paint wear

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MOTORGUIDE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by MotorGuide and may not be distributed or copied, digitally or otherwise, without the prior written consent of MotorGuide.

Correction

Replace with bracket of the new design.



a - Newly designed part

Parts Required

Qty: 1 MRK01108 (Black) MRK01109 (White)

Warranty

Credit will be issued to dealers for the cost of parts and labor through October 31, 2005. Submit a warranty claim through your normal warranty processing channel, listing:

00300

- Trolling motor model number and serial number
- · Quantity and part numbers of parts used

Flat Rate Codes SB05 0.5 hour

Part Code 851Failure Code 27

USA and Canada – Tag and hold all old parts until 30 days after credit issued or until notified to return them.

International – Follow instructions for old parts disposition issued by the Marine Power International office or by your distributor.

This document is provided for the sole and exclusive use of the original recipient as prescribed by MotorGuide and may not be distributed or copied, digitally or otherwise, without the prior written consent of MotorGuide.

Page 2 of 2 OCTOBER 2002 2002-18