



service information

ADVISORY
 BULLETIN

No. 2001-12

Circulate to: Sales Manager Accounting Service Manager Technician Parts Manager

Fuel Additive Recommendation (Quickleen)

Models Affected

MERCURY/MARINER/TRACKER
135 THRU 225 HP, Optimax
S/N 0G590000 and Above

Today's OptiMax engine control systems allow only minute quantities of air and fuel to reach the combustion chamber in order to produce minimal emissions. But, these diminutive amounts of air and fuel are easily obstructed by fuel injector, direct injector and combustion chamber deposits. Due to the inconsistent fuel quality in some areas, excessive fuel system and combustion chamber deposits are on the rise. These deposits cause many driveability problems that range from hesitation, rough idle, spark plug fouling, to detonation problems.

This performance characteristic can be prevented through fuel system maintenance.

Correction

To minimize fuel system, and carbon deposit buildup in the engine, we recommend adding Mercury or Quicksilver Quickleen P/N 92-802877A1 Engine Treatment additive to your engine's fuel at each tank fill, throughout the boating season. Use additive as directed on the container.