



# Service Bulletin

Bulletin No. 2014-07  
OEM No. 2014-02

Circulate to:  Sales Manager  Accounting  Service Manager  Technician  Parts Manager

## Blockage of Oil Drain Tube

### Models Affected

Models Covered	Serial Number
200/225/250/300/350 SCi Verado L6	2B030543-2B131909
200/225/250/300/350 SCi Verado L6	Belgium - 0P587498-0P592600

### Scope

Worldwide

### Situation

During the first oil change the oil may fail to drain, due to blockage of the oil drain tube with casting core sand. If no obstruction is found no further action is needed.

### Solution

Insert a flat blade screwdriver into the open end of the drain tube and rotate the screwdriver while exerting a moderate amount of pressure to clear the blockage. Draining oil will purge any sand in the tube.

### Parts Required

No parts required.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.