



Service Bulletin

Bulletin No. 2014-04
OEM No. 2014-01

Circulate to: Sales Manager Accounting Service Manager Technician Parts Manager

Cowl Mounted Trim Switch

Models Affected

Models Covered (Non-Race)	Serial Number
30/40 2-Cyl	1B932866–2B086556
30/40 EFI FourStroke	1C199138–1C266376
30/40 FourStroke	1C198988–1C229227
40 4-Cyl EFI FourStroke	1C205011–1C274485
40/50 3-Cyl (674)	0N181000–0N183991
40 Classic	0N180946–0N218741
50/60 EFI FourStroke	1C199565–1C274506
55/60 3-Cyl (674)	1B931260–2B099460
75/90	1B936951–2B089161
75/90/115 1.5L DFI	1B973560–1B964749
75/90/115 EFI L4NA FourStroke	1B944565–2B083159
75/90/115 EFI 2.0L FourStroke	2B095166–2B097424
115 EFI FourStroke	1B968532–1B968653
115 Pro XS	1B935262–2B110723
115–175 2.5L DFI	1B935491–1B965891
125 1.5L DFI	1B974623–2B110224
135–200 L4 Verado	1B940452–2B041100
150/175/200 2.5L EFI	1B964546–2B091948
150 FourStroke	1B943613–2B082397
150 Pro XS	1B935209–2B110683
175 Pro XS	1B935735–2B110302
200/225/250 3.0L EFI	1B935126–2B092306
200–250 3.0L DFI	1B935024–2B088436
200–300 L6 Verado	2B027214–2B029637
200 Pro XS	1B935119–2B110718
225/250 Pro XS	2B013788–1B974762
350 SCi Verado	1B939389–2B028672

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.

Cowl Mounted Trim Switch

Models Covered (Race)	Serial Number
60 FourStroke	1C202125–1C267376
200 XS	1E051934–1E052279
250 Sport XS	1E051651–1E052185
300 XS	1E051720–1E052293
3.0L JP	1E051835–1E052335
200 XS SST	1E051932–1E052262
3.0L SID	1E052347–1E052341

Scope

Worldwide

Situation

If a customer comes in with a failure of the tilt switch (mushy, inoperative, unintended operation, or any failure) on any outboard built between June 2012 and May 2014, the switch should be replaced.



56340

Parts Required

Part Number	Description
8M0037225	Trim switch
8M0042300	Trim switch
8M0042301	Trim switch

Warranty

United States and Canada

File a claim on MercNET.

Return switch to Mercury for warranty.

Parts and labor will only be covered during the engine's warranty period.

Outside the United States and Canada

Follow the instructions issued by your local office or distributor.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.