

service bulletin

No. 97-7

Warm Engine Start Up Procedure on Hi-Performance 2.5 EFI with Digital ECU

Models Affected

All Hi-Performance 2.5 electronic fuel injected with digital ECU.

Problem

Possible difficulty starting a warm or hot Hi-Performance 2.5 EFI engine.

Recommendation

- 1. After the engine has been run and is warmed up, the following restart procedure should be followed. When restarting a warm 2.5 EFI.
- 2. With remote control in neutral position, open throttle plate slightly a 1/16 to 1/8 inch and start engine.
- 3. After engine starts, immediately return advanced throttle position lever to normal position.