

WARRANTY INFORMATION     SERVICE INFORMATION  
 PARTS INFORMATION

Bulletin No. 2003-02

Circulate to:    Sales Manager    Accounting    Service Manager    Technician    Parts Manager

## Motor Mount Adaptor Plate (Part # MPLT0001) – No Longer Available (NLA)

### Models Affected

All PINPOINT Trolling Motors (models 3300, 3700 & 3900)

### Situation

The PINPOINT motor mount adaptor plate is no longer available.

### Correction

When a replacement is needed, the complete mount assembly needs to be ordered.

### Parts Required

MST921BF for models 3300, 3700 & 3900 with 42 or 50 inch shaft

MST924BF for models 3700 & 3900 with 60 inch shaft

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MOTORGUIDE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by MotorGuide and may not be distributed or copied, digitally or otherwise, without the prior written consent of MotorGuide.