

#### Bulletin No. 2005-02

Circulate to:

Sales Manager

Accounting

Service Manager

Technician

Parts Manager

# 16 Breakaway Mount

# Models Affected


All MST91642A and MST91642S 16 Breakaway mounts

### Situation

Under certain conditions, the set screws holding the bow arm and top channel to the deck channel become loose.

## Correction

If you service these mounts, the set screws holding the bow arm to the deck channel and the top channel to the deck channel must be reset using Loctite® 242 Blue. The bottom two threads of the screw should be completely covered with Loctite®.



# **Parts Required**

Tube Ref No	Description	Where Used	Part No.
66 🗇	Loctite 242 Threadlocker	Set screws	92-809821

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.

## Warranty

MotorGuide will credit the service center for the cost of parts and labor as outlined in this bulletin until March 31, 2008. Submit a warranty claim through your normal warranty processing channel listing:

- Model and Serial number of the trolling motor
- Five tenths (0.5) hour labor
- Warranty Flat Rate Code: SB01
- Part Code: 851
- Failure Code: 20

#### **US AND CANADA**

Complete/process claim via MercNET or a warranty claim form. Mercury Marine P.O. Box 1939 Fond du Lac, WI 54936 Fax 1-920-929-5893

#### INTERNATIONAL

Follow instructions issued by the Marine Power International Office or by your distributor.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.