

Circulate to:  Sales Manager  Accounting  Service Manager  Technician  Parts Manager

## 21 and 24 Mount Lock Slide

### Models Affected


All 21 and 24 Bow Mount Units

### Situation

Lock pins may come loose and slide to either side of the bow arm making it difficult to lock and unlock.

### Correction

The lock slide assembly for these mounts has been updated and new pins are required when installing the new assembly.




16548

Old lock slide assembly

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.

The new lock slide assembly is a combination of metal and plastic and the old lock slide pins will not work in the new assembly.



16549

New lock slide assembly

### Parts Required

Qty.	Description	Part Number
1	21 mount lock slide assembly kit	MRK31304S
1	24 mount lock slide assembly kit	MRK31305S

### Warranty

Repairs will be covered until June 30, 2008.

Complete the warranty claim providing:

- Model and serial number of the trolling motor
- Proof of purchase of the 21 and 24 mount
- 0.5 hour labor
- Warranty flat rate code: SB05
- Part code: 851
- Failure code: 20

### US AND CANADA

Complete/process claim via MercNET or return a warranty claim form.

Mail to:

Mercury Marine  
P.O. Box 1939  
Fond du Lac, WI 54936  
Fax 1-920-929-5893

### International

Follow the instructions issued by the Marine Power International Office or by your distributor.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.