

TO: PARTS MANAGER
SERVICE MANAGER

No. 91-2

A. QUICKSILVER 1991 ACCESSORIES GUIDE 90-42000-91, Top of Page 128

Change

Oil Cooler Kit (Part No. 85152A2) is listed for use with MCM 5.7 Litre Bravo Two closed cooling kits (Part No. 91036A1 & A8). This kit must be installed on these models if they are operated in water that is 90° F (32° C) or warmer. In water temperatures below 90° F (32° C), this kit is not required. If the oil cooler is used on these models when operating in cold water, the oil temperature may not reach the optimum operating temperature.

Please make this note in your Quicksilver 1991 Accessories Guide.