

Service Bulletin

Bulletin No. 2009-11

Circulate to:	Sales Manager	Accounting	Service Manager	Technician	Parts Manager

25/30 HP FourStroke Voltage Regulator/Rectifier Test Specifications

Models Affected

Description	Part Number
25/30, 25 Jet FourStroke Service Manual	899182R01

Situation

Mercury Marine has received updated troubleshooting specifications for the voltage regulator/rectifier in the above listed service manual. Please use the revised specifications shown on the following page when troubleshooting the voltage regulator/rectifier on the affected models.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.

Meter Test I	_eads	Meter Scale	Reading
Red	Black	→	
	Yellow	→	Ouch
	Black	→	Ouch
Red	Yellow	→	Ouch
	Yellow	→	Ouch
	Red	→	0.4–0.8
4	Black	→	1.0–1.7
Yellow ^{1.}	Yellow	→	1.6–1.9
	Yellow	→	1.6–1.9
	Red	→	0.8–1.3
	Yellow	→	0.4–0.8
Black	Yellow	→	0.4–0.8
	Yellow	→	0.4–0.8

Correction

Included with this bulletin is an adhesive backed sheet containing the corrected tables that can be cut out and applied to **Section 2B - Charging and Starting System** in your service manual. Please use the corrected table to update the manual until the next service manual revision occurs.

1. Each yellow lead must be tested

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.

Page 2 / 2 © 2009 Mercury Marine AUGUST 2009 2009-11