

Revised 6-25-85

NUMBER: 85-12

CIRCULATE TO:
SERVICE MANAGER
PARTS MANAGER
MECHANICS
"Place in a Service
Bulletin Binder"

- A. Tune Up Slide Chart - 1979 and Newer MerCruiser Engine
- B. Spark Plug Wire Sets

A. TUNE UP SLIDE CHART - 1979 and NEWER MERCUISER ENGINES

A new Tune Up Slide Chart for MerCruiser engines, is now available. This new chart covers 1979 and newer models except the MCM 185/205 MR. The older chart also is still available.

90-71288 - 1978 and older MerCruiser Models
90-42798 - 1979 and newer MerCruiser Models

B. SPARK PLUG WIRE SETS

Complete sets of spark plug wires are now available for many MerCruiser models. Each set contains all spark plug wires fully assembled and ready for installation on the engine. Coil hi-tension wire is not in sets. Order from following chart.

IMPORTANT: Spark plug wires, on Thunderbolt IV (H.E.I.) Ignition system, have the same type of connector on each end, however, wires must be installed only one way. Black boot end goes on distributor cap and Gray boot end goes on spark plug.

MODEL	PART NUMBER
MCM 120/140	84-43376A5
MCM 150/160/165	84-43376A8
MCM/MIE 470, MCM 170/485/488/190	84-43376A6
MCM 185 (229 CID V-6)	84-43376A7
Thunderbolt IV (HEI) MCM 185/205 (262 CID V-6)	84-43376A11 (Note 1)
Conventional Ignition MCM 888/215/225/233/255 (Ford) MIE 215/225/233/255 (Ford) MCM 898/228/250/260/280 (GM) MIE 198/228/255 (GM)	84-43376A9
Thunderbolt IV (HEI) MCM 898/200/228/230/260 MIE 230/260 (LH Rot.)	84-43376A4 (Note 1)
Thunderbolt IV (HEI) MIE 230/260 (RH Rot.)	84-43376A3 (Note 1)
Conventional Ignition MCM 330/370/400/400 Cyclone MIE 330	84-43376A10
Thunderbolt IV (HEI) MCM 330 (B-W) MIE 340 (LH Rot.)	84-43376A2 (Note 1)
Thunderbolt IV (HEI) MIE 340 (RH Rot.)	84-43376A1 (Note 1)

Note 1: Refer to IMPORTANT.