

## Service Bulletin

					Bulletin No. 2011-04
Circulate to:	Sales Manager	Accounting	Service Manager	Technician	Parts Manager

## Pro Series Tracker Cover Sets No Longer Available (NLA)

## Models Affected

The following Pro Series Tracker covers are limited to current stock on hand and then will no longer be available (NLA).

Pro Series Models	Part Number	
TX40, TX45, MP4300	MM5917	
TX50, TX55, MP5200	MM5916	
TX60, TX65, TX70, MP6700	MM5915	

## Correction

When replacing a cover for an older Pro Series Tracker model, refer to the current Pro Series Tracker parts listing. Replace both top and bottom covers. Replace attaching hardware as required. Decals for older style Pro Series Tracker models are no longer available (NLA).

The following Pro Series Tracker covers are available.

Pro Series Model	Top Cover Part Number	Bottom Cover Part Number	
Pro 46	MTF05341T	M899372T	
Pro 54	MTF05341T	M899372T	
Pro 70/75	MTF05341T	M899372T	

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.

2011-04 NOVEMBER 2011 © 2011 Mercury Marine Page 1 / 1