

## service bulletin

TO: SERVICE MANAGER ☐ PARTS MANAGER ☐

MECHANICS □

Revised 2-18-93 No. 89-8

## **Custom Propeller Service From Mercury Hi-Performance**

Many of today's hi-performance boaters demand the ultimate from their equipment, including the propellers installed on their boat.

Mercury Hi-Performance Group (MHPG) has responded to this need by providing propeller repair, blueprinting, and customizing of Quicksilver Cleaver, Laser, Mirage, and Chopper propellers. This service is for stainless steel propellers, used exclusively on Mercury, Mariner and MerCruiser products.

Propellers serviced by Mercury Hi-Performance Group will be detailed and finished by highly skilled propeller craftsmen. With proper care, they will offer maximum performance and reliability.

For estimates on custom propeller work, contact Dennis Cavanaugh at 414/921/5330. Cavanaugh and his propeller technicians represent over 40 years of experience in propeller design and repair.

Propellers should be shipped to:
Mercury Hi-Performance Group
1970 Aeromarine Drive
P.O. Box 1458
Fond du Lac, Wi 54936-1458

Phone: 414-921-5330 Fax: 414-921-6533

IMPORTANT: MHPG propeller service is strictly for the dealer that has a customer who requires a finely tuned, custom finished, or blueprinted propeller for a specific application. We are not a propeller repair outlet for Quicksilver Laser, Mirage, High 5 or Chopper propellers.

Any questions on Quicksilver propeller warranties, repairs, prices, or availability should be handled through your normal service and distribution channels.

Quicksilver propellers sent to Mercury Hi-Performance Group for warranty inspection and adjustment will then be forwarded to the proper departments. This will delay decisions and credits to

our customers. Inquiries on prices and availability of stock propellers will also be forwarded to the proper departments. Normal propeller repairs should be handled through a local propeller repair outlet.

Please distribute this bulletin to all appropriate personnel.

Printed in U.S.A. 89-8 293