

TO: PARTS MANAGER
SERVICE MANAGER

No. 95-3

Trim Pump Supersession-Super Speedmaster Drives

Models

All III SSM, IV SSM and V SSM Drives

Parts Catalog and Cards Affected by Change

Parts catalog:

90-13668 MerCruiser SSM/Alpha SS Drives
Revised March 1994
Page 39 and 43

Parts card:

Card no. 36 Grid C14 & D4
Stern Drives MC Super/Speedmaster/Alpha-one SS
Revised April, 1994

Ordering Correct Trim Pump

MerCruiser Super Speedmaster Stern Drives were originally sold with a Prestolite trim pump. The part number for a complete replacement pump is 92975A6. This pump is NLA and is superseded to P/N 92975A28 which is an Oildyne pump that does not have enough Out/Up pressure to allow trimming the drive while underway.

The correct replacement pump for the 92975A6 Prestolite pump is the Oildyne pump 846859A4. This is also a complete pump with solenoids and mounting bracket. Remounting of the Oildyne pump in the boat will be required because of mounting bracket differences.