



parts bulletin



No. 96-14

REPLACEMENT PARTS L-DRIVE TRIM & TILT PUMP MOTOR F722541 AND F695541-1

Force L-Drive (1989 Thru 1992 Models) (85/90 & 120/125 HP)

REF. NO.	PART NO.	QTY.	DESCRIPTION
1	F17629	1	MOTOR ASSY (With Bayonet Connectors For F695541-1) (Replace Bayonet Connectors To Bullet Connectors For F722541)
2	89493	1	COUPLING
3	F17631	1	O RING
4	F17632	1	ADAPTER ASSEMBLY
5	F17633	1	PUMP ASSEMBLY
6	F17634	2	FILTER
7	F17639	1	VALVE KIT-Thermal
8	812498A1	1	VALVE KIT-High Pressure
9	812499A1	1	VALVE KIT-Low Pressure
10	F17635	1	RESERVOIR ASSEMBLY
11	25- 17645	1	O RING
12	36- 18526	1	CAP
13	F17638	1	MOUNTING KIT (Screw & Spacer & O Ring)

