

Circulate to: Sales Manager Accounting Service Manager Technician Parts Manager

MerCruiser Gasoline Engine Oil Filter Part Number Mislabeled Models Affected

Model	Serial Number
MerCruiser gasoline engines, excluding 4.3L V6 engine without a remote oil filter	All

Situation

A quantity of Mercury branded oil filters, part number 35-866340K01, were packaged with part number 35-866340K01 printed on the box and the part number 35-897669K01 printed on the filter.



19405

Mislabeled filter superseded to current



19406

Current Mercury branded filter

Ordering Replacement Parts

Part number 35-897669K01 has been superseded to 35-866340K01. The parts are of the same construction and either one may be used as a service replacement.

THE INFORMATION IN THIS DOCUMENT IS CONFIDENTIAL AND PROTECTED BY COPYRIGHT AND IS THE PROPERTY OF MERCURY MARINE.

This document is provided for the sole and exclusive use of the original recipient as prescribed by Mercury Marine and may not be distributed or copied, digitally or otherwise, without the prior written consent of Mercury Marine.